DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1x.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015247 Address: 333 Burma Road **Date Inspected:** 28-Jun-2010

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 800 **OSM Departure Time:** 1000 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

CWI Name: Mike Johnson **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: PQR**

Summary of Items Observed:

This Quality Assurance (QA) Inspector, Craig Hager was on site at the job site between the times noted above. This QA Inspector was on site to randomly observe and witness the welding of a Procedure Qualification Record (PQR) test plate and monitor the Quality Control (QC) functions.

This QA Inspector met with QC Inspector Mike Johnson and was informed the welding had been completed during the second shift of work the previous work day, the strong backs had not been removed and the final visual inspection of the weld had not been performed. Prior to this QA Inspector Danny Reyes provided this QA Inspector a turnover confirming the completion of welding. QC Inspector Mike Johnson said he would inform this QA Inspector when the strong backs had been removed and the final visual inspection completed.

later, QC Inspector Mike Johnson informed this QA Inspector the PQR test plate had been visually inspected and accepted. This QA Inspector performed a random visual verification and the weld appeared to comply with the contract requirements. Please see Welding Witness Report (6032)this date for details.

Summary of Conversations:

As noted above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mohammad Fatemi (916) 813-3677, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By: Hager,Craig Quality Assurance Inspector **Reviewed By:** Levell,Bill QA Reviewer